11/07/201	9		Maria de Maria de Maria					3 2 3 TT	Pa	ge	1
			lte	emized Proper	ty C	osts					
From Tab	ole: MAIN Se	ction 1						Recor	rd # 1508		
Property ID:			#: 696-221-12	106 Last Ins	pec	ted: 03/27/	/2012	Cos	t Update:)5/31/2	016
	DURST WILLI	AM G		Sale Price:	1	186,000	Book:	438	Validity:	Yes	
	NOLF ASHLE			Sale Date:			Page:	133-1			
	22 RANDALL			Bldg Type:	Sin		Quality:	3.00	AVERAG	E	
City/St/Zip: \				Style:			Frame:	Stude	led		
	22 RANDA			Area:	170)4	Yr Built:	1890	_	129	
Description:		/L		# Rms:	6		# Bedrm:	: 3	# Ktchns	: 1	
Tax Map #:				# 1/2 Bath:	1		# Baths:	1			
Item		De	escription	Percer	nt	Quantity	Unit	Cost		Tota	al ——
BASE COS	ST										
Exterior W	all #1:	Hardb	ord / Ht=8	100.0	00			73.04			
ADJUSTM	ENTS										
Roof #1:		C	CompShg	100.0	00						
Subfloor			Wood	SEA JACOBS	_			0.40			
Floor cove	er #1:	9.13	llowance	100.0				3.48			
Heat/cooli	ng #1:	H/	N BB/ST	100.0	00			1.78			
Energy Ad	justment		Average				_ 3	70.00		400.4	2
ADJUSTE	BASE COS	Γ				1,704.00)	78.30		133,42	23
ADDITION	AL FEATURE	S									
Fixtures (b	eyond allow	ance of 8)				a same	-	10.00			
Roughins	(beyond allov	wance of 1)				1.00	-	85.00			35
Dormers			Shed roof			10.00		52.50		1,52	
Porch #1:		WoodDck/Scree				66.00		53.22		3,5	
Porch #2:		WoodDck/NoWa				119.00		33.98		4,04	
Basement			Stone			648.00)	22.44		14,54	
Subtotal										157,53	50
Local mult				1.0							
Current mi	-			1.0	10					157,53	20
REPLACE	MENT COST									107,00	
Condition		A	vg/Good	Percei						20.20	2
	epreciation			25.0						-39,38 -23,63	
Functional	depreciation	1		15.0							
	depreciation	0202 878 88 88		15.0	U					-23,63 70,90	
REPLACE	MENT COST I	NEW LESS DEPR					D	/D - + -		70,90	
LAND PRIC	CES		Size	Nbhd Mu		Grade	•	/Kate		62.00	00
SI Bldg Lo	t		0.07	1.0	0	0.90	J			63,00	
Total			0.07							63,00	
SITE IMPR	OVEMENTS	Hsite/Hstd		Qualit	-					7.00	00
Water		y / y	Typical	Averag						7,00	
Sewer		y / y	Typical	Averag						10,00	
Landscape)	y / y	Typical	Below Av	'g					3,00	
Total										20,00	JU
OUTBUILD	INGS	Hsite/Hstd	% Good	Siz		Rate		xtras			
			40	24	7	18.60	1			4.60)()

 OUTBUILDINGS
 Hsite/Hstd
 % Good
 Size
 Rate.
 Extras

 DGS 1.5S
 y / y
 40
 247
 18.60
 4,600

 Total
 4,600
 4,600
 4,600

TOTAL PROPERTY VALUE

NOTES

HOUSESITE VALUE: . 158,500

NOTES HOUSESITE VALUE: . 156,500 HOMESTEAD VALUE: . 158,500

FLOODPLAIN - 5% ECONOMIC. 1/2 OF A DUPLEX 10% FUNC, ASBESTOS SIDING, NEW REPLACEMENT WINDOWS, 1/2 BATH & KITCHEN.

2

11/01/20	10							
Itemized Property Costs								
From Ta	able: MAIN Section 1		Record # 1508					
Property ID: 920-0022V		Span #: 696-221-12106			7/2012 Cost Update: 05/31/2016			
Owner(s):	DURST WILLIAM G		Sale Price:	186,000	Book:	438	Validity:	Yes
Owner(s).	WOLF ASHLEY		Sale Date:	06/07/2019	Page:	133-1		
Address:	22 RANDALL ST		Bldg Type:		Quality:	3.00	AVERAG	E
	WATERBURY VT 05676		Style:	2.5U (SF)	Frame:	Stude		-
Location:	22 RANDALL ST		Area:	1704	Yr Built:	1890	Eff Age:	129
	:0.07 AC & DWL		# Rms:	6	# Bedrm:	3	# Ktchns	: 1
	19-337.000		# 1/2 Bath:	1	# Baths:	1		
Item		Description	Percer	nt Quantity	, Unit	Cost		Total

2012: FLOOD DAMAGE HAS NOT BEEN REPAIRED - NO KITCHEN - TRIM WORK TO DO - BSMT STILL A MESS -HEAT NOT DONE - CALL 80% COMPLETE - ADD 15% ECONOMIC - LOWER NC TO 1.1.

2013: REPAIRS FINISHED AFTER FLOOD.

2014: ADDED 3RD FLOOR - +5% FUNC FOR THIRD FLOOR. 30% ECONOMIC FOR 10 YEAR FLOODPLAIN. OVERALL CONSIDERED IN AVERAGE/GOOD CONDITION WITH THE REPAIRS DONE. LOWERED NC TO 1.0.

2016: Reduced economic to 15% from 30% on floodplain properties for equity purposes.