
PHOTOGRAPHS OF SUBJECT PROPERTY



FRONT VIEW OF FARMHOUSE DUPLEX



REAR VIEW OF FARMHOUSE DUPLEX

Description of Improvements – Farmhouse Duplex:

CHRONOLOGICAL AGE:

100± years

GROSS USABLE AREA:

2,702± Square Feet

TYPE:

Wood frame building

BASEMENT:

Full stone foundation

FOUNDATION:

Stone

ROOF:

Steel

EXTERIOR WALLS:

Wood Clapboard

LAYOUT:

One 3-bedroom and one 2-bedroom

apartment.

WINDOWS:

Double hung and casement. Thermopane

with screens

INTERIOR WALLS:

Sheetrock and plaster

CEILINGS:

Sheetrock and plaster

FLOORING:

Wood floors, ceramic tile and vinyl

HEATING SYSTEM:

Baseboard hot water

AIR CONDITIONED:

None


ELECTRICAL:


Typical for occupancy

OVERALL CONDITION:

Good

SKETCH OF FARMHOUSE FLOORPLAN





Comments:

Access to this duplex was not available to the appraiser. Descriptions are based on information provided by Mr. Besser, town records and viewing of the exterior.

The house is an older farmhouse that has been largely renovated in the past two years. It had been vacant for some time prior to purchase by Gretchen Besser and required many repairs. Interior finishes have been largely replaced or refinished. The two units are appealing and functional, with average to above average quality. Mechanical systems were recently replaced or upgraded. Exterior finishes have been refinished and new windows were installed.

PHOTOGRAPHS OF SUBJECT PROPERTY




FRONT VIEW OF SINGLE FAMILY RESIDENCE



REAR VIEW OF SINGLE FAMILY RESIDENCE

SKETCH OF RESIDENCE FLOORPLAN



Comments:

This building was formerly an outbuilding of the farm, but has been entirely renovated into a single-family residence. Exterior finishes were repaired or replaced where needed and dormers were added to the second floor. The structure was completely insulated. Interior finishes are entirely new and of average quality. Mechanical systems are new as well.

Description of Improvements - Single Family Residence:

CHRONOLOGICAL AGE:

Shell is in excess of 50± years, but interior is

new.

GROSS USABLE AREA:

1,272± square feet

TYPE:

Wood frame building

BASEMENT:

Poured concrete slab

FOUNDATION:

Poured concrete

ROOF:

Steel

EXTERIOR WALLS:

Wood Clapboard

LAYOUT:

Main Floor: Kitchen, Dining Area, Living Room, Laundry & Pantry/Utility Room Second Floor: 2 bedrooms and a full bath

WINDOWS:

Double hung single pane with screens and

fixed single pane windows

INTERIOR WALLS:

Sheetrock with softwood trim

CEILINGS:

Sheetrock

FLOORING:

Carpet and vinyl

HEATING SYSTEM:

Oil fired hot water boiler with domestic hot

water

AIR CONDITIONED:

None

ELECTRICAL:

Typical for occupancy

OVERALL CONDITION:

Good