
Scoping Condition Report



Working Dog Septic Service 504 Fletcher rd Cambridge, Vt 05444 1 (888) 949-9969

Job Site:	
suo porthund noth nevo	
nath her	

Job Requirements:	

	Date:	Preformed By:
Scoping Analysis:		TREprese
scoped from Septie Tout to Treatmen	it pos	
O to 20' Pipe has 44 + seg		
0 to 20' pipe has 4" t seg 20 to 45' pipe is in good condition		
Scoped from Spolic Tente is home		
8 to 20' pipe has 411 + sogg 8 to 20' pip is in good Condition		
8'to 20' pip is is good Cocilition		

THIS SCOPING REPORT INDICATES THE PRESENT CONDITION OF THE SEPTIC SYSTEM, ACCORDING TO EVALUATOR'S OPINION; AT THE TIME OF THE INSPECTION.

THIS CONDITION REPORT DOES NOT GARENTEE OR WARRANTY FUTURE PERFORMANCE. WORKING DOG SEPTIC SERVICE INC. DISCLAIMS ANY WARRANTY EITHER EXPRESSED OR IMPLIED ARISING FROM THE INSPECTION OF THE SEPTIC SYSTEM OR THIS REPORT.

Evaluator's Signature:

Working Dog Septic Service Inc.

504 Fletcher Road

1-888-949-9969

Cambridge, VT 05444

1-802-343-1657

SYSTEM CONDITION REPORT			
Date: 4/2/21 Time:	Name of Evaluator:		
Name: Property A	address: Sqo northballouth horo		
Access Provided Into The House: Recent Weather Conditions:	Yes No Tank Size: 1000 Gallons		
	PROCEDURES		
Determined sludge depth and liqu	uid level		
Probed and checked absorption area to determine location and checked for			
exessive moisture, and/or odor.			
Pumped out tank			
Checked condition of tank and baffles/tees for cracks, deterioration or damage			
Properly closed tank cover			
Liquid Level in tanks was: Above No	turn turn turn turn turn turn turn turn		
Did water drain back intot the tank from the			
Yes			
Maintenance appears: Good	h-respect		
Type of System	Type of Tank Typer of Absorption System		
Septic Tank (Number of Tanks)	Concrete Leaching Field		
Cesspool	Steel Raised Mound		
Advanced Treatment System	Plastic Seepage Pit		
Other	Other Other		
SYSTEM COMPONENTS	COMMENTS		
TANK OR CESSPOOL	Septic Tento is in good		
Condition:	lando o da dota		
Acceptable Unacceptable	caralyas		
PUMP			
Condition: Acceptable Unacceptable			
Not Applicable ABSORPTION SYSTEM			
Condition:			
Acceptable Unacceptable			
Acceptable			
THIS CONDITION REPORT INDICATES THE PRESENT CONDITION OF THE SEPTIC SYSTEM			
ACCORDING TO EVALUATOR'S OPINION, AT THE TIME OF THE PUMPING/INSPECTION.			
THIS CONDITION REPORT DOES NOT GARENTEE OR WARRANTY FUTURE PERFORMANCE.			
WORKING DOG SEPTIC SERVICE INC. DISCLAIMS ANY WARRANTY EITHER EXPRESSED OR			
IMPLIED ARISING FROM THE INSPECTION OF THE SEPTIC SYSTEM OR THIS REPORT.			
10			
Evaluator's Signature:			