



Twin City Subaru
 142 Berlin Mall Road
 Berlin, VT 05602
 PH: (802) 223-5232

34810 CLA

PATRICIA K. CLARK		VEHICLE ID		MILES IN	MILES OUT	DATE/TIME IN	DATE OUT	INVOICE NO.
98 STERLING WOODS RD		4S4BSADC1H3222825		13111	13112	07/15/17 07:45	07/15/17	34810
STOWE, VT 05672		VEHICLE DESCRIPTION				TAG NO.	STATUS	
patti@gminn.com		2017 SUBARU OUTBACK (TGM TUNGST)				04190	COMPLETE	
CONTROL NO.	LICENSE PLATE NO.	CUST. LABOR RATE	PROD. DATE	IN-SERV DATE	DELIV. DATE	DELIV. MILES	TERMS	
9251		VARI		08/23/16	08/23/16	50	Cash	
HOME PHONE	WORK PHONE	CELL PHONE	STOCK NO.	SERV. ADV.			RO COMMENT	
(802) 253-8952	(802) 253-4400	(802) 279-0563	T11873	DAN ROYEA (44)				

Line	Op-Code	Fail Code	Tech	Hours	Type	Amount
A *	MPI		A00		Internal	
Concern MULTI-POINT VEHICLE INSPECTION						

B *	100661	JQQ90	A00		Serv. Cont.	
Concern PERFORM SUBARU REQUIRED LEVEL 2 SERVICING - OIL CHANGE, TIRE ROTATION, REPLACE CABIN AIR FILTER AND GENERAL SERVICING PER SERVICE CONTRACT 100-661 JQQ90 .7H \$119.34						
Cause SERVICE DUE						
Correction LEVEL 2 SERVICE COMPLETE						

Part Number	Description	Qty.
15208AA15A	OIL FILTER COMPLETE	1
803916010	GASKET	1
SOA635045	SYNTHETIC 0W-20 OIL QT	6
72880AL00A	FILTER	1

C *	MB4		A00		Customer	\$69.95
Concern MOUNT AND BALANCE 4 TIRES						
Correction MOUNT AND BALANCE COMPLETE						
Line Total...						\$69.95

D +	VSIF		A00		Internal	
Concern VERMONT STATE INSPECTION						
Correction VSI COMPLETE						
Misc. Code	Description	Qty.				
STCKR	VSI STICKER COST	1.0				

PATRICIA K. CLARK 98 STERLING WOODS RD STOWE, VT 05672 patti@gminn.com		VEHICLE ID		MILES IN	MILES OUT	DATE/TIME IN	DATE OUT	INVOICE NO.	
		4S4BSADC1H3222825		13111	13112	07/15/17 07:45	07/15/17	34810	
		VEHICLE DESCRIPTION					TAG NO.	STATUS	
		2017 SUBARU OUTBACK (TGM TUNGST)					04190	COMPLETE	
CONTROL NO.	LICENSE PLATE NO.	CUST. LABOR RATE	PROD. DATE	IN-SERV DATE	DELIV. DATE	DELIV. MILES	TERMS		
9251		VARI		08/23/16	08/23/16	50	Cash		
HOME PHONE	WORK PHONE	CELL PHONE	STOCK NO.	SERV. ADV.			RO COMMENT		
(802) 253-8952	(802) 253-4400	(802) 279-0563	T11873	DAN ROYEA (44)					

Authorized Estimates

Date/Time	Amount	Authorized By	Authorization Method	Phone/Email	Adv. Username
07/15/2017 07:45	\$74.85		Initial Estimate		danro

Totals

	Amount
Misc Supplies	\$4.90
SalesTax	\$0.29
Labor	\$69.95
TOTAL CREDIT CARD	\$75.14

STATEMENT OF DISCLAIMER

The factory warranty constitutes all of the warranties with respect to the sale of this item/items. The Seller hereby expressly disclaims all warranties either express or implied, including any implied warranty of merchantability or fitness for a particular purpose. Seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of this item/items.

On behalf of servicing dealer, I hereby certify that the information contained hereon is accurate unless otherwise shown. Warranty services described were performed at no charge to owner. There was no indication from the appearance of the vehicle or otherwise, that any part repaired or replaced under this claim had been connected in any way with any accident, negligence, or misuse. Records supporting this claim are available for (1) year from the date of payment notification at the servicing dealer for inspection by manufacturer's representative.

X _____ Customer Signature	_____ Dealer, General Manager, or Authorized Person. (Date)
-------------------------------	--

MULTI-POINT INSPECTION

Customer: PATRICIA K. CLARK

E-mail: patti@gminn.com

Phone: (802) 253-8952

RO #: 34810

Date: 07/15/2017

VIN: 4S4BSADC1H3222825

Plate:


Mileage: 13,111

Year/Make/Model: 17 SUBARU OUTBACK

www.VTCars.com
TWIN CITY
Subaru Central in Vermont☒ Checked and OK at this time☐ May require future attention☐ Requires immediate attention**FLUID LEVELS****OK | FILL**☒ ☐ Engine Oil☒ ☐ Brake Reservoir☒ ☐ Coolant**OK | FILL**☐ ☐ Transmission (if equipped)☐ ☐ Power Steering☒ ☐ Windshield Washer**INTERIOR COMPONENTS**☒ ☐ Cabin Air Filter☒ ☐ Dome Light / Amp Light / Dimmer Combination Meter☒ ☐ Parking Brake Operation**EXTERIOR COMPONENTS**☒ ☐ Horn Operation☒ ☐ Head Lights / Tail Lights / Turn Signals / Brake Lights / Hazards / Exterior Lamps☒ ☐ Windshield Wiper & Washer Operation☒ ☐ Windshield Glass (cracks / damage)☒ ☐ Fuel Tank Cap Gasket☒ ☐ Wiper Blades**UNDER-VEHICLE COMPONENTS**☒ ☐ Engine Air Filter☒ ☐ Propeller / Driveshaft (damage/leaks/U-joints)☒ ☐ Drive / CV Shaft (damage/leaks/boots)☒ ☐ Axle Hub & Bearing (damage/leaks/noise)☒ ☐ Suspension (damage/leaks/wear)☒ ☐ Hoses (cracks/damage/leaks)☒ ☐ Cooling System (leaks)☒ ☐ Steering Linkage (damage/leaks/wear)☒ ☐ Fluid Leaks (engine/transmission/differential)☒ ☐ Exhaust System (damage/leaks/corrosion)☒ ☐ Fuel Lines, Connections, Tank Bands, Vapour Vent System Hoses (damages/leaks/corrosion)☒ ☐ Drive Belts (cracks/damage/leaks)☒ ☐ Radiator Core / Air Conditioning Condenser**SIGNATURES**

SERVICE ADVISOR

SERVICE TECHNICIAN

MAINTENANCE ITEMS**DUE**☐ Oil & Filter Change☐ Engine/Secondary Coolant☐ Check Air Filter Minder☐ Transmission Fluid**DUE**☐ Tire Rotation☐ Fuel Filters☐ Transmission Filter☐ Drain Water Separator**BATTERY CHECK**☒ ☐ Battery Health (good, recharge, bad) Cold Cranking Amps (Actual)☒ ☐ Battery Condition (clamps, cables, corr...) Cold Cranking Amps (Factory Spec)**EXTERIOR BODY**

DRIVER SIDE

BIRDS-EYE

PASSENGER SIDE

TIRES & BRAKES**Left Front**☒ ☐ Tire Wear Pattern/Damage☒ ☐ Tire Pressure set to factory-specs
0 PSI☒ ☐ Tire Tread Depth 8/32"☒ ☐ Brake Lining 7mm | DISC**Right Front**☒ ☐ Tire Wear Pattern/Damage☒ ☐ Tire Pressure set to factory-specs
0 PSI☒ ☐ Tire Tread Depth 8/32"☒ ☐ Brake Lining 7mm | DISC**Left Rear**☒ ☐ Tire Wear Pattern/Damage☒ ☐ Tire Pressure set to factory-specs
0 PSI☒ ☐ Tire Tread Depth 8/32"☒ ☐ Brake Lining 6mm | DISC**Right Rear**☒ ☐ Tire Wear Pattern/Damage☒ ☐ Tire Pressure set to factory-specs
0 PSI☒ ☐ Tire Tread Depth 8/32"☒ ☐ Brake Lining 6mm | DISC**Spare Tire**☒ ☐ Tire Wear Pattern/Damage☒ ☐ Tire Pressure set to factory-specs
0 PSI☒ ☐ Tire Tread Depth 0/32"**Tire Wear Indicates**☐ Check Tire Alignment☐ Balance Wheels☐ Tire Repair Needed**COMMENTS**

Department of Motor Vehicles
Agency of Transportation
<http://dmv.vermont.gov/AVIP>


DMV inspections
120 State Street
Montpelier, Vermont 05603-001

VEHICLE IDENTIFICATION

Plate: GTL423	Year: 2017	GVWR: 5001
VIN: 4S4BSADC1H3222825	Make: SUBARU	Sticker Number: 17-638017
Veh. Type: CAR/TRUCK	Model: OUTBACK	Sticker Month: 8
Odometer: 13111	Fuel Type: GASOLINE	

OVERALL TEST RESULT: PASS
OBD-II INSPECTION RESULT: PASS

System Monitored	Status	Test Results	
Misfire	Ready	OBDII Connection:	PASS
Fuel System	Ready	OBD Readiness Monitor Results:	PASS
Comprehensive	Ready	MIL Check with Key On-Engine Off:	PASS
Catalyst	Ready	MIL Check with Engine Running:	PASS
Heated Catalyst	Not Applicable	MIL Command Status:	PASS
Evaporative System	Ready	Diagnostic Trouble Codes(DTC) if Present	
Secondary Air	Not Applicable		
Air Conditioning System	Not Applicable		
Oxygen Sensor	Ready		
Oxygen Sensor Heater	Ready		
EGR System	Ready		

Station #: 895	Primary Tech #: 8405	Date: 07/15/2017
Station Name: BERLIN AUTOMOTIVE S1,LLC	Tech name: TIMOTHY COLES	Time: 09:28:52
Station Address: 142 BERLIN MALL RD.	Primary Technician	
Secondary Tech #:	Signature: 	
Tech Name:		

Department of Motor Vehicles
Agency of Transportation
<http://dmv.vermont.gov/AVIP>

DMV inspections
120 State Street
Montpelier, Vermont 05603-001

VEHICLE IDENTIFICATION

Plate: GTL423	Year: 2017	GVWR: 5001
VIN: 4S4BSADC1H3222825	Make: SUBARU	Sticker Number: 17-638017
Veh. Type: CAR/TRUCK	Model: OUTBACK	Sticker Month: 8
Odometer: 13111	Fuel Type: GASOLINE	

The AVIP system has not identified any open recalls for your vehicle. Please check with the vehicle manufacturer, dealership or the repair facility for potential recalls for your vehicle.



**Reference
Number**

Type

Recall Description

What is a recall?

When a manufacturer, the National Highway Traffic Safety Administration (NHTSA), or the Environmental Protection Agency (EPA) determines that a car or item of motor vehicle equipment creates an unreasonable risk to safety or fails to meet minimum safety standards, or an emission control component is not functioning properly, the manufacturer is required to fix that car or equipment at no cost to the consumer.

What should I do if my vehicle is included in this recall?

If your vehicle is included in this recall, **it is very important that you get it fixed as soon as possible given the potential danger to you and your passengers if it is not addressed.**

You should receive a separate letter in the mail from the vehicle manufacturer, notifying you of the recall and explaining when the remedy will be available, whom to contact to repair your vehicle or equipment, and to remind you that the repair will be done at no charge to you.

If you do not receive a letter in the mail from the vehicle manufacturer, please contact your vehicle manufacturer or dealership or for safety items you may also call NHTSA's Vehicle Safety Hotline at 1-888-327-4236.

Thank you for doing your part to help keep Vermont's highways safe and our air clean.