₩ RD		VEHICLE ID 4S3BNAC68H3054527			МІ	MILES IN MILES OUT DA			TE/TIME IN	DATE OUT	INVOICE NO.	
					1.	14775 14776 05/0		05/09	9/18 06:49	05/09/18	46049	
, u567	2		VE	HICLE DES	CRIPT	ION			TAG NO.	ST	ATUS	
_y.clark@pallsper		2017 SUBARU	LEG	ACY 2.5	(CR	YSTAL	BL)		02390	COM	PLETE	
CONTROL NO.	LICENSE PLATE NO.	CUST. LABOR RATE	PRC	D. DATE	IN-SE	ERV DATE DELIV. DATE		TE	DELIV. MILES	TERMS		
080794	HAB906	VARI			04/	/07/17 04/07/17		7	6	Cash		
HOME PHONE	WORK PHONE	CELL PHONE		STOCK N	Ο.		SERV.	ADV.		RO	COMMENT	
		(802) 598-8936	3	T1262	9	W	ILLIAM L	INDIE	E (46)			

		Α	utho	rized Es	timat	es					<u> </u>	
Date/Time	zed By	rization Me	ethod	Phone	/Email			Adv. l	Jsername			
05/09/2018 06:49	\$74.85		Estimate	nate					blindie			
		To a dia							Totals			
										Amou	ınt	
					Labor Total Amount Due					\$69.95 \$69.95		
						CREDIT	CABD		·	\$69.95		
				, '	OTAL	CILDII	CAND			φ0:	7.95	
										- <u>-</u>		
TATEMENT OF DISCLAIM	MER	.		On b	ehalf of	servicing	dealer, I here	by certi	ify that the infor	mation contain	ed hereon is	
ne ractory warranty o the sale of this :	constitutes all of the self-	ne warranties with er hereby expressl	resp Y	charg	ale un je to ov	vner. The	wise snown. Yere was no ind	varrant ication f	ty services desc from the appear	rance of the ve	formed at no hicle or otherwise, any way with any	
mplied warranty of s	ties either express of merchantability or fi	tness for a partic	ular	accid	ent, ne	allaence.	or misuse. Re	ecoras s	supportina this i	ciaim are availa	able for (1) year	
ssume for it any lia	ther assumes nor autho ability in connection	orizes any other p with the sale of	erson this	manı	irie dat ifacture	e of paym er's repres	entative.	ı at the	servicing deale	a ioi inspectior	i by	
tem/items.												
^	Customer Signatur			-		Dealo	r General Ma	nager o	or Authorized P	erson. (Da	te)	
	Oustomer Signatur	-				eaie	., General Ma	nayer, (o Authorizeu P	Ulauli. (Da		



Twin City Subaru 142 Berlin Mall Road Berlin, VT 05602 PH: (802) 223-5232

		VEHICLI	E ID	MILES IN	MILES OUT	DA	TE/TIME IN	DATE OUT	INVOICE N
OWE, VT 05672	ERLING WOODS RD		4S3BNAC68H3054527			14776 05/09		05/09/18	46049
OWE, VT 05672							TAG NO.	STATUS	
oy.clark@pallsper	a.com	2017 SUBARU L	EGACY 2.5	(CRYSTA	L BL)		02390		PLETE
CONTROL NO.	LICENSE PLATE NO.	CUST. LABOR RATE	PROD. DATE	ROD. DATE IN-SERV DAT		DELIV. DATE		ELIV. MILES TERI	
080794	HAB906	VARI		04/07/17	04/07/	17	6		Cash
HOME PHONE WORK PHON		CELL PHONE	STOCK	IO.	SERV	SERV. ADV.			COMMENT
		(802) 598-8936	T1262	9 V	VILLIAM L	INDIE	E (46)		
Line Op-C	ode Fail C	Code Tec	h Hou	rs Typ	е		А	mount	
Concern MULT Correction MPI (TI-POINT VEHICLE COMPLETE	E INSPECTION							
B * ME	34	A39)	Custor	mor			\$69.95	
					1	_ine 1	Γotal	\$69.95	:
C * 1006		90 430		Com. C		_ine 1	Γotal	\$69.95	
ROT <i>A</i> MENU 10066	FORM SUBARU R ATION, REPLACE J 51 JQQ90 119.32	EQUIRED LEVEI CABIN AIR FILT	_ 2 SERVIC	Serv. C CING - OIL ENERAL S	ont.	E, TIF	RE	\$69.95	:
Concern PERF ROTA MENU 10066 Cause SERV	FORM SUBARU R ATION, REPLACE J 51 JQQ90 119.32	EQUIRED LEVEI CABIN AIR FILT	_ 2 SERVIC	ING - OIL	ont.	E, TIF	RE	\$69.95	:
Concern PERF ROTA MENU 10066 Cause SERV	FORM SUBARU R ATION, REPLACE J 51 JQQ90 119.34 IICE L 2 SERVICE COM	EQUIRED LEVEI CABIN AIR FILT	_ 2 SERVIC	ING - OIL	ont.	E, TIF	RE	\$69.95	
Concern PERF ROTA MENU 10066 Cause SERV Correction LEVE	FORM SUBARU R ATION, REPLACE J S1 JQQ90 119.34 FICE L 2 SERVICE COM	EQUIRED LEVEI CABIN AIR FILT 4 .7 IPLETED	_ 2 SERVIC ER AND G	ING - OIL	ont. CHANGE SERVICIN	E, TIF	RE	\$69.95	:
Concern PERF ROTA MENU 10066 Cause SERV Correction LEVE	FORM SUBARU R ATION, REPLACE J S1 JQQ90 119.34 FICE L 2 SERVICE COM	EQUIRED LEVEL CABIN AIR FILT 7.7 MPLETED Description	_ 2 SERVIC ER AND G	ING - OIL	ont. CHANGE SERVICIN Qty.	E, TIF	RE	\$69.95	
Concern PERF ROTA MENU 10066 Cause SERV Correction LEVE	FORM SUBARU R ATION, REPLACE J S1 JQQ90 119.34 FICE L 2 SERVICE COM	EQUIRED LEVEL CABIN AIR FILT 1.7 IPLETED Description ELEM CP OIL F GASKET	2 SERVICER AND G	CING - OIL ENERAL S	Ont. CHANGE SERVICIN Qty. 1	E, TIF	RE	\$69.95	
Concern PERF ROTA MENU 10066 Cause SERV Correction LEVE Part Number 15208AA12A 803916010	FORM SUBARU R ATION, REPLACE J S1 JQQ90 119.34 FICE L 2 SERVICE COM	EQUIRED LEVEL CABIN AIR FILT 4 .7 IPLETED Description ELEM CP OIL F	2 SERVICER AND G	CING - OIL ENERAL S	ont. CHANGE SERVICIN Qty.	E, TIF	RE	\$69.95	:

Description

VSI STICKER COST

Misc. Code

STCKR

Qty.

1.0