



**NA Manosh Inc**  
120 Northgate Plaza  
Morrisville, VT 05661  
Phone: (802) 888-5722  
Fax: (802) 888-4681

# Invoice

Invoice Number
36671
Invoice Date
4/19/2023

**Bill To:** Matthias Bohler  
617 Covered Bridge Rd  
  
Stowe, VT 05672

**Re:**

Job No	Customer Job No	Customer PO	Payment Terms	Technician(s)	Service Date
23HYDRO			<b>Due Upon Receipt</b>	Ben/Oran Jr	04/17/23
Quantity	Description		U/M	Rate/Unit	Price

04/17/23 - Jetting/Septic Pumping/Septic Inspection

1.00	Jetter/Camera Technician - 1st Hour	HR	270.00	270.00
1,300.00	Disposal Per Gallon	GAL	0.35	455.00

\*\* Finished digging tank and pumped. Scoped inlet and found offset 2 feet from clear out where pipe went from cast to PVC. Unable to scope outlet as it was under a shrub and inaccessible.

\*\* Cake Level 4 inches - Sludge Level 6 inches

**Please make checks payable to N.A. Manosh Inc.**


New drilled wells, new shallow wells, new driven well point, new springs or deepening existing groundwater sources now require testing the water before using it. Please see the Water Supply Rule at the following link:

[dec.vermont.gov/sites/dec/files/dwgwp/rorules/pdf/Wastewater-System-and-Potable-Water-Supply-Rules-April-12-2019.pdf](http://dec.vermont.gov/sites/dec/files/dwgwp/rorules/pdf/Wastewater-System-and-Potable-Water-Supply-Rules-April-12-2019.pdf)

Subtotal	\$	725.00
Sales Tax (if applicable)	\$	0.00
Payments to Date	\$	0.00
Deposit	\$	0
<b>Total Due</b>	<b>\$</b>	<b>725.00</b>

*Thank you for your business!*





www.manosh.com  
800-544-7666

# NA Manosh Inc

120 Northgate Plaza  
Morrisville, VT 05661  
Phone: (802) 888-5722  
Fax: (802) 888-4681

N A MANOSH INC  
120 NORTHGATE PLAZA  
MORRISVILLE, VT 05661  
802-888-5722  
41399801261097

Merchant ID: 1097  
Term #: 0001

Store #: 1  
Ref #: 1

## Sale

XXXXXXXXXXXX2798

VISA

Entry Method: Ma

Total: \$ 725.

Bill To: Matthias Bohler  
617 Covered Bridge Rd  
Stowe, VT 05672

Re:

04/19/23 15:2  
Inv #: 000007 Appr Code: 07  
Transaction ID: 583109701425043  
Apprvd: Online Batch#: 06  
AVS Code: ZIP MATCH Z  
CVV2 Code: MATCH M

Customer Copy

THANK YOU!

Job No	Customer Job No	Customer PO	Payment Terms	Tech
23HYDRO			Due Upon Receipt	Ben/
Quantity	Description	U/M	Rate	

04/17/23 - Jetting/Septic Pumping/Septic Inspection

1.00	Jetter/Camera Technician - 1st Hour	HR	270
1,300.00	Disposal Per Gallon	GAL	0.3

\*\* Finished digging tank and pumped. Scoped inlet and found offset 2 feet from clear out where pipe went from cast to PVC. Unable to scope outlet as it was under a shrub and inaccessible.

\*\* Cake Level 4 inches - Sludge Level 6 inches

PAID

Please make checks payable to N.A. Manosh Inc.

New drilled wells, new shallow wells, new driven well point, new springs or deepening existing groundwater sources now require testing the water before using it. Please see the Water Supply Rule at the following link:

[dec.vermont.gov/sites/dec/files/dwgwp/rorules/pdf/Wastewater-System-and-Potable-Water-Supply-Rules-April-12-2019.pdf](http://dec.vermont.gov/sites/dec/files/dwgwp/rorules/pdf/Wastewater-System-and-Potable-Water-Supply-Rules-April-12-2019.pdf)

Subtotal	\$	725.00
Sales Tax (if applicable)	\$	0.00
Payments to Date	\$	0.00
Deposit	\$	0.00
Total Due	\$	725.00

Thank you for your business!





120 Northgate Plaza  
Morrisville, VT 05661  
(800) 544-7666  
(802) 888-5722  
(802) 888-4681 Fax  
nickm@manosh.com

## SEPTIC INSPECTION REPORT

NAME: Matthias Bohler

DATE: 4/17/23

ADDRESS: 617 Covered Bridge Road Stowe

TANK SIZE : 1300

TANK DEPTH : 24 inches

RISERS : No                      FILTER : No

BAFFLES : INLET- Concrete good condition    OUTLET- No Access

TANK CONDITION : Good

INLET LINE : Cast Iron/PVC

INLET CONDITION : Fair

INLET DISTANCE: 18 Feet

OUTLET LINE : Unknown

OUTLET CONDITION : Unknown

OUTLET DISTANCE: Unknown

COMMENTS: System operating at normal level at time of inspection.

1300 gallon ledge style septic tank

Inlet line has a slight line sag 2 feet from the septic tank.

Inlet line has 1 ½ inch offset just outside house foundation.

Outlet cover of septic tank is under a shrub and inaccessible.