

6/6/15	- All 3 tanks pumped	\$ 930.00
9/8/11	- all 3 tanks pumped	\$ 935.00
12/15/06	- Commercial pump	684.93
3/29/12	† - Jetting Service	505.00
7/25/06	- Jetting Service (Apt 4)	150.00
7/6/10	- Clear obstruction	225.00
7/25/06	- Jetting Service (Apt 4)	243.56
2/27/09	- Pump & Jet	475.00

92117

Stagecoach Apartments
Robert Beattie
1115 North Hollow Road
Stowe, VT 05672

82
223
3252

Stagecoach Apartments
11 Stagecoach Road
Stowe, VT 05672

MARK BROOKS

Sludge Level: 8 inches Cake Level: 6 inches Tank was over full Tank does not have a filter	
Tank on side of house Baffles: Appear good Tank Condition: Appears good Number of hoses used: 2 Depth of Tank: 12 inches Sludge Level: 4 inches Cake Level: 10 inches	
Walk way tank Baffles: Appear good Tank Condition: Appears good Number of hoses used: 2 Depth of Tank: 48 inches Sludge Level: 6 inches	

Sentic Tank Pumping*Line Cleaning and Jetting*Household Drain	C1		\$0	F	1 E	1 P		
---	----	--	-----	---	-----	-----	--	--

6/16/2015

92117

Bill To

Stagecoach Apartments
 Robert Beattie
 1115 North Hollow Road
 Stowe, VT 05672

Job Site

Stagecoach Apartments
 11 Stagecoach Road
 Stowe, VT 05672

Work Order No	Purchase Order No	Service Rep	Service Date	Terms	Due Date
T37278	Robert	Billy	6/15/2015	Net 30	7/16/2015
Quantity	Description			Rate	Amount
	Cake Level: 24 inches Appeared to have rags in the tank				
	Disposal Location: Montpelier WWTP				
1,200	Commercial Pumping - Parking Lot Tank			0.275	330.00
1,000	Commercial Pumping - Tank on side of house			0.275	275.00
1,000	Commercial Pumping - Walk way tank			0.275	275.00
1	Dig Fee Parking Lot Tank - During the covering and uncovering of your septic tank, soils may settle after a period of time which could create a hazard. It is recommended these soils be replaced to avoid any potential injuries.			50.00	50.00
Thank you for choosing Hartigan.				Total	\$930.00
				Balance Due	\$930.00

Hartigan offers complete wastewater solutions

Environmentally safe and responsible disposal

Septic Tank Pumping*Line Cleaning and Jetting*Household Drain Cleaning*Grease Traps and 1/2" to 1" Pipes

Stagecoach Apartments
Robert Beattie
1115 North Hollow Road
Stowe, VT 05672

Transaction		Date	Amount	Balance		
INV #92117. Orig. Amount \$930.00.		06/16/2015	930.00	930.00		
INV #FC 8579. Orig. Amount \$6.88. Finance Charge		07/31/2015	6.88	936.88		
CURRENT		1-30 DAYS PAST DUE	31-60 DAYS PAST DUE	61-90 DAYS PAST DUE	OVER 90 DAYS PAST DUE	Amount Due
6.88		930.00	0.00	0.00	0.00	\$936.88

A service charge equivalent to 1.5% per month

Date	Invoice #
9/8/2011	47982

Bill To:

Stagecoach Apartments
Robert Beattie
1115 North Hollow Road
Stowe, VT 05672

Job Site:

11 Stagecoach Road
Stowe, VT 05672

Phone #	P.O. No.	Service Rep:	Service Date	Terms	Due Date
(802) 223-3452	Bob	Shawn	9/7/11	Net 30	10/8/2011
Quantity	Description			Rate	Amount
1	Service Call				
1.3	Labor Rate			75.00	75.00
3,000	Commercial Pumping			150.00	195.00
	Coupon / Reminder Card Discount			0.225	675.00
	Technician's Comments:			-10.00	-10.00
	Jettied main line, pipe was leaking above 1st floor.				
	Pipe was clear.				
	Changed wax gasket for Apt 2, stopped the leak.				
	Plumbing may need to be changed for Apartment #2 if leak starts again				
	The line goes from lead to cast iron pipe.				
	Driver's Comments:				
	Tank Condition: Appears good				
	Number of hoses used: 2				
	Depth of Tank: 3'				
	Sludge Level: 4"-6"				
	Cake Level: 4"-8"				
	Disposal Location: Stowe WWTP				
	*Map on File				
Thank you for choosing Hartigan.			Total		\$935.00
			Balance Due		\$935.00

paid 10/27/11
CH 676

Hartigan offers Complete Wastewater Solutions
Environmentally Safe and Responsible Disposal
Septic Tank Pumping*Line Cleaning and Jetting*Household Sewer Cleaning

Bill To:

Stagecoach Apartments
Robert Beattie
1115 North Hollow Road
Stowe, VT 05672

Job Site:

11 Stagecoach Road
Stowe, VT 05672

Phone #	P.O. No.	Service Rep:	Service Date	Terms	Due Date
(802) 223-3452	Bob	Shawn	9/7/11	Net 30	10/8/2011
Quantity	Description			Rate	Amount
1	Service Call			75.00	75.00
1.3	Labor Rate			150.00	195.00
3,000	Commercial Pumping			0.225	675.00
	Coupon / Reminder Card Discount			-10.00	-10.00
	Technician's Comments: Jetted main line, pipe was leaking above 1st floor. Pipe was clear. Changed wax gasket for Apt 2, stopped the leak. Plumbing may need to be changed for Apartment #2 if leak starts again. The line goes from lead to cast iron pipe.				
	Driver's Comments: Tank Condition: Appears good Number of hoses used: 2 Depth of Tank: 3' Sludge Level: 4"-6" Cake Level: 4"-8" Disposal Location: Stowe WWTP Map on File				
	Thank you for choosing Hartigan.			Total	\$935.00
				Balance Due	\$935.00

Hartigan offers Complete Wastewater Solutions
Environmentally Safe and Responsible Disposal

Septic Tank Pumping*Line Cleaning and Jetting*Household Drain Cleaning*Grease Trap and Tank Pumping*Pump

Bill To
Stagecoach Apartments Robert Beattie 1115 North Hollow Road Stowe, VT 05672

P.O. No.	Terms	Serviced by:	Service Date
Robert	Net 15	JR	12/14/2006


Quantity	Description	Rate	Amount
3,500	Commercial Pumping		
1	Fuel Surcharge based on NE PAD	0.185	647.50
	Site Location: Stagecoach Apartments	37.43	37.43
	Drivers Comments:		
	Pumped 1000 gallon tank		
	Pumped (2) 750 gallon tanks		
	Pumped 1000 gallon tank at house		
	Total gallons pumped: 3500		
	Baffles: Good		
	Baffles not plugged with grease		
	Tank Condition: Good		
	Maintenance Plan: Call In		
	Disposal Location: Riverside WWTP		
	Riser: Yes		
	Sludge Level: 6"		
	Cake Level: 6-8"		
Total			\$684.93

ou for your business.

N. 06-1518107

Phone #	Fax #
---------	-------

Stagecoach Apartments
Robert Beattie
1115 North Hollow Road
Stowe, VT 05672

					Amount Due
					\$565.00
Transaction		Date	Amount	Balance	
INV #51904. Due 03/29/2012. Orig. Amount \$565.00.		02/28/2012	565.00	565.00	
					
CURRENT	1-30 DAYS PAST DUE	31-60 DAYS PAST DUE	61-90 DAYS PAST DUE	OVER 90 DAYS PAST DUE	Amount Due
565.00	0.00	0.00	0.00	0.00	\$565.00
A service charge equivalent to 1.5% per month (18% per year) will be added to past due accounts. NEW REMITTANCE ADDRESS					

Bill To
Stagecoach Apartments Robert Beattie 1115 North Hollow Road Stowe, VT 05672

P.O. No.	Terms	Serviced by:	Service Date
Robert	Net 15	TA	7/24/2006

Quantity	Description	Rate	Amount
1	Jetting Service Site Location: Unit #4 Stagecoach Road Stowe VT Unit #4 has plugged line Technician's Comments: Jetted from apartment clean out to the tank It was clogged Runs fine now	0.00 150.00 0.00	0.00 150.00 0.00
Thank you for your business.		Total	\$150.00

Paid
9/18/06

T.I.N. 06-1518107


Phone #	Fax #
----------------	--------------

Bill To:

Stagecoach Apartments
Robert Beattie
1115 North Hollow Road
Stowe, VT 05672

Job Site:

Route 100
Stage Coach Road

P.O. No.	Terms	Service Rep:	Service Date	Phone #	Fax #
Robert Beatie	Net 30	MB	7/2/10	(802) 223-3452	(802) 223-6116
Quantity	Description			Rate	Amount
1	Service Call			75.00	75.00
1	Labor Rate			150.00	150.00
<p>Technician's Comments: Jetted from clean out in ceiling but did not clear obstruction. Jetted from bathroom sink drain in unit #3 to clear obstruction.</p> 					
Please note our new mailing address. Our remittance address has changed.			Thank you for choosing Hartigan.	<p><i>Ok.</i> Total 388</p> <p><i>paid</i> <i>7/31/10</i></p> <p>\$225.00</p>	


Hartigan offers Complete Wastewater Solutions
Environmentally Safe and Responsible Disposal

Septic Tank Pumping*Line Cleaning and Jetting*Household Drain Cleaning*Grease Trap and Tank Pumping*Pump

Date	Invoice #
7/25/2006	14800

Bill To
Stagecoach Apartments Robert Beattie 1115 North Hollow Road Stowe, VT 05672

P.O. No.	Terms	Served by:	Service Date
Robert	Net 15	TA	7/24/2006

Quantity	Description	Rate	Amount
1	Service Call	75.00	75.00
1	Jetting Service	150.00	150.00
1	Fuel Surcharge based on NE PAD	18.56	18.56
Site Location: Unit #4 Stagecoach Road Stowe VT Unit #4 has plugged line Technician's Comments: Jetted from apartment clean out to the tank It was clogged Runs fine now			
			
Thank you for your business. T.I.N. 06-1518107		Total \$243.56	

Phone #	Fax #
---------	-------

JOB SITE:

up 7 clogged tub drain

Name: Stage Coach Apartment

A: Stowe

Zip _____

Ph: _____

1. Baffles: Good _____ Not Good: _____
2. Baffles plugged with Grease: Yes _____ No: _____
3. Tank Condition: Good _____ Fair: _____ Replace _____
4. # of Hoses to reach tank from truck: _____
5. Recommended maintenance plan: _____
6. Disposal Location: _____

BILLING: liquid level 6" below, in p.

Name: Robert M. Beattie SR

A: 1115 North Hollow Rd

Stowe 1/4 06672 Zip _____

Ph: (w) _____ h _____

Tank Size: _____ COV / UNC

Tank Overfull. Pumped _____ additional gallons

Metal: _____ Concrete: _____ Other: _____

Serviced by: _____ Svc Date: _____

Depth: _____ Riser: _____

METHOD OF PAYMENT:

Homeowner notified payment required at time of service: YES / NO

Location of payment: _____

Cash _____ Check #: _____ Credit Card: VISA or MC

Card #: _____ Exp: _____

OK To Invoice Customer: _____ Rate: _____

PROBLEMS OR COMMENTS

No: _____ Yes: JETTED From Apartment clean out TO The TANK
was clogged now runs fine

DIRECTIONS:

MapPage: (_____) STARTING FROM: "TODD"

ADA

Fuel Surcharge

Effective July 1, 2005, your fee for liquid waste services will include a fuel surcharge. Given the extraordinary volatility surrounding fuel/oil prices nationwide, combined with the fact that fuel/oil is a significant portion of the investment we make every day to provide you with outstanding services, this surcharge allows us to keep up with the cost of meeting that obligation to you.

This calculation will be obtained by using an index-based surcharge that will be adjusted monthly. The surcharge is based on the Regional U.S. Average On-Highway Diesel Fuel Prices reported by the U.S. Department of Energy. As an ongoing reference, this table may be obtained by downloading information at the following web site:

www.eia.doe.gov/pub/oil_gas/petroleum/data_publications/weekly_petroleum_status_report/current/pdf/table17.pdf

As you will see from the published index, the surcharge could be adjusted monthly, depending on the index fluctuation, either up or down. Depending on the price of fuel, it is possible that the fuel/oil surcharge could be \$0.00 in any given month.

This fuel surcharge will be broken out as a separate item on your invoices.

Your continued understanding and support is greatly appreciated.

Sincerely,

Carl R. Bailin

Carl R. Bailin
President

Bill To
Stagecoach Apartments Robert Beattie 1115 North Hollow Road Stowe, VT 05672

P.O. No.	Terms	Serviced by:	Service Date
Robert	Net 15	TA	7/24/2006

Quantity	Description	Rate	Amount
1	Jetting Service Site Location: Unit #4 Stagecoach Road Stowe VT Unit #4 has plugged line Technician's Comments: Jetted from apartment clean out to the tank It was clogged Runs fine now	0.00 150.00 0.00	0.00 150.00 0.00
Thank you for your business.		Total	\$150.00

Paid
9/18/06

T.I.N. 06-1518107

Phone #	Fax #

To:

Stagecoach Apartments
 Robert Beattie
 1115 North Hollow Road
 Stowe, VT 05672

Terms	Due Date	Amount Due	Amount Enc.
Net 15	1/13/2007	\$684.93	684.93

Date	Transaction				Amount	Balance
12/15/2006	INV #16563. Due 12/30/2006. Orig. Amount \$684.93. --- CP, 3,500 @ \$0.185 = 647.50 --- Fuel Surcharge, 1 @ \$37.43 = 37.43 --- Site Location: Stagecoach Apartments Drivers Comments: Pumped 1000 gallon tank } apt. Pumped (2) 750 gallon tanks Pumped 1000 gallon tank at house Total gallons pumped: 3500 Baffles: Good Baffles not plugged with grease Tank Condition: Good Maintenance Plan: Call In Disposal Location: Riverside WWTP Riser: Yes Sludge Level: 6" Cake Level: 6-8" --- Tax: Non @ 0.0% = 0.00				684.93	684.93
CURRENT	1-30 DAYS PAST DUE	31-60 DAYS PAST DUE	61-90 DAYS PAST DUE	OVER 90 DAYS PAST DUE	Amount Due	
684.93	0.00	0.00	0.00	0.00	684.93	

IF YOU HAVE ANY QUESTIONS, PLEASE CALL.

Phone #	Fax #
802 252 0056	

Paid

To:

Stagecoach Apartments
 Robert Beattie
 1115 North Hollow Road
 Stowe, VT 05672

Terms	Due Date	Amount Due	Amount Enc.
Net 15	1/13/2007	\$684.93	684.93

Date	Transaction				Amount	Balance
12/15/2006	INV #16563. Due 12/30/2006. Orig. Amount \$684.93. --- CP, 3,500 @ \$0.185 = 647.50 --- Fuel Surcharge, 1 @ \$37.43 = 37.43 --- Site Location: Stagecoach Apartments Drivers Comments: Pumped 1000 gallon tank Pumped (2) 750 gallon tanks } apt. Pumped 1000 gallon tank at house Total gallons pumped: 3500 Baffles: Good Baffles not plugged with grease Tank Condition: Good Maintenance Plan: Call In Disposal Location: Riverside WWTP Riser: Yes Sludge Level: 6" Cake Level: 6-8" --- Tax: Non @ 0.0% = 0.00				684.93	684.93
CURRENT	1-30 DAYS PAST DUE	31-60 DAYS PAST DUE	61-90 DAYS PAST DUE	OVER 90 DAYS PAST DUE	Amount Due	
684.93	0.00	0.00	0.00	0.00	684.93	

IF YOU HAVE ANY QUESTIONS, PLEASE CALL.

Phone #	Fax #
802-253-0276	802-253-0287

Paid
 1/13/07

7/25/2006

14800

Bill To

Stagecoach Apartments
 Robert Beattie
 1115 North Hollow Road
 Stowe, VT 05672

P.O. No.

Terms

Serviced by

Service Date

Robert

Net 15

TA

7/24/2006

Quantity

Description

Rate

Amount

1 Service Call

75.00

75.00

1 Jetting Service

150.00

150.00

1 Fuel Surcharge based on NE PAD

18.56

18.56

Site Location: Unit #4 Stagecoach Road Stowe
 VT

Unit #4 has plugged line

Technician's Comments:

Jetted from apartment clean out to the tank

It was clogged

Runs fine now

Thank you for your business.

Total

\$243.56

T.I.N. 06-1518107

Phone #

Fax #

To:

Stagecoach Apartments
 Robert Beattie
 1115 North Hollow Road
 Stowe, VT 05672

Terms	Due Date	Amount Due	Amount Enc.
Net 15	1/13/2007	\$684.93	684.93

Date	Transaction				Amount	Balance
12/15/2006	INV #16563. Due 12/30/2006. Orig. Amount \$684.93. --- CP, 3,500 @ \$0.185 = 647.50 --- Fuel Surcharge, 1 @ \$37.43 = 37.43 --- Site Location: Stagecoach Apartments Drivers Comments: Pumped 1000 gallon tank } apt. Pumped (2) 750 gallon tanks Pumped 1000 gallon tank at house Total gallons pumped: 3500 Baffles: Good Baffles not plugged with grease Tank Condition: Good Maintenance Plan: Call In Disposal Location: Riverside WWTP Riser: Yes Sludge Level: 6" Cake Level: 6-8" --- Tax: Non @ 0.0% = 0.00				684.93	684.93
CURRENT	1-30 DAYS PAST DUE	31-60 DAYS PAST DUE	61-90 DAYS PAST DUE	OVER 90 DAYS PAST DUE	Amount Due	
684.93	0.00	0.00	0.00	0.00	\$684.93	

IF YOU HAVE ANY QUESTIONS, PLEASE CALL.

Phone #	Fax #
800-252-0256	800-252-0256

Paid
 1/15/07

Bill To:
 Robert Beattie
 1115 North Hollow Road
 Stowe, VT 05672

Job Site:
 Stagecoach Apartments
 Route 100 & Stage Coach Road
 Stowe, VT 05672

P.O. No.	Terms	Service Rep:	Service Date	Phone #	Fax #
Robert	Due on receipt	Multi	2/26/09	802-253-0376	802-253-0387

Quantity	Description	Rate	Amount
1,000	Commercial Pumping		
1	Service Call	0.25	250.00
1	Jetting Service	75.00	75.00
		150.00	150.00
Driver's Comments: Baffles: couldn't see Tank Condition: appears good Sludge Level: 2"-3" Cake Level: 2"-3" Disposal Location: Montpelier WWTP Technician's Comments: Jetted from tank to building Line was plugged with grease No Sales Tax			
		0.00%	0.00
Please note our new mailing address. Our remittance address has changed.		Thank you for choosing Hartigan.	Total \$475.00

Hartigan offers Complete Wastewater Solutions
 Environmentally Safe and Responsible Disposal
 Septic Tank Pumping*Line Cleaning and Jetting*Household Drain Cleaning*Grease Trap and Tank Pumping*Pump
 Station Repair*Catch Basin & Storm Drain Cleaning*Closed Circuit TV Camera Inspection*E

*pd 3/30/09
ck 631*

Bill To:

Stagecoach Apartments
Robert Beattie
1115 North Hollow Road
Stowe, VT 05672

Job Site:

11 Stagecoach Road
Stowe, VT 05672

Phone #	P.O. No.	Service Rep:	Service Date	Terms	Due Date
(802) 223-3452	Bob	Shawn	9/7/11	Net 30	10/8/2011
Quantity	Description			Rate	Amount
1	Service Call			75.00	75.00
1.3	Labor Rate			150.00	195.00
3,000	Commercial Pumping			0.225	675.00
	Coupon / Reminder Card Discount			-10.00	-10.00
	Technician's Comments:				
	Jetted main line, pipe was leaking above 1st floor.				
	Pipe was clear.				
	Changed wax gasket for Apt 2, stopped the leak.				
	Plumbing may need to be changed for Apartment #2 if leak starts again				
	The line goes from lead to cast iron pipe.				
	Driver's Comments:				
	Tank Condition: Appears good				
	Number of hoses used: 2				
	Depth of Tank: 3'				
	Sludge Level: 4"-6"				
	Cake Level: 4"-8"				
	Disposal Location: Stowe WWTP				
	*Map on File				
	Thank you for choosing Hartigan.			Total	\$935.00
				Balance Due	\$935.00

Hartigan offers Complete Wastewater Solutions

Environmentally Safe and Responsible Disposal

Septic Tank Pumping*Line Cleaning and Jetting*Household Drain Cleaning*Grease Trap and Tank Pumping*Pump
Station Repair*Catch Basin & Storm Drain Cleaning*Closed Circuit TV Camera Inspection*Frozen Line

Bill To:
Stagecoach Apartments Robert Beattie 1115 North Hollow Road Stowe, VT 05672

Job Site:
11 Stagecoach Road Stowe, VT 05672

Phone #	P.O. No.	Service Rep:	Service Date	Terms	Due Date
(802) 223-3452	Bob	C.S.	2/27/12	Net 30	3/29/2012
Quantity	Description			Rate	Amount
1	Service Call			75.00	75.00
3	Labor Rate			150.00	450.00
1	Misc. Parts			40.00	40.00
Technician's Comments: Land lord requested we start jetting from apartment #4, clean out was in the bathroom ceiling, this did not clear the line in apartment #2. Tried to jet from tub, but could not get through the trap. Cut lav. drain apart to access pipe. Jetted line several times until line cleared. Reassembled sink and tested line. Line is draining properly.					
Thank you for choosing Hartigan.				Total	\$565.00
				Balance Due	\$565.00

Hartigan offers Complete Wastewater Solutions
Environmentally Safe and Responsible Disposal

Septic Tank Pumping*Line Cleaning and Jetting*Household Drain Cleaning*Grease Trap and Tank Pumping*Pump
Station Repair*Catch Basin & Storm Drain Cleaning*Closed Circuit TV Camera Inspection*Freezer Line