

HARTIGAN COMPANY
 O BOX 1134, STOWE, VT 05672
 www.hartigancompany.com



800-698-0761
 802-253-0376 Local
 802-253-0387 Fax

SYSTEM CONDITION REPORT

Date: 4/4/07 Time: 2:42 PM Name of Evaluator: GUY W. CYR
 Name: LEO WEISS Property Address: 399 SUGAR HOUSE HILL RD. STOWE VT.
 Access Provided Into House ☐ Yes ☒ No Tank Size 1250 gallons
 Recent Weather Conditions: _____

PROCEDURES (CHECK APPROPRIATE BOXES)

- ☒ Locate, Uncovered, and Accessed Tank
☒ Determined sludge depth and liquid level (If liquid level above or below normal level DO NOT PUMP)
☐ Probed and checked absorption area to determine location and checked for excessive moisture, effluent, and/or odor
☒ Pumped out tank
☐ Checked condition of tank and baffles/tees for cracks, deterioration or damage. If applicable, checked cesspool walls for settlement and/or partial cover.
☒ Properly closed tank cover
☒ Returned the removed sod (returned earth to as close to original condition as possible)

Liquid level in tank is: ☐ Above Normal ☒ Normal ☐ Below Normal Sludge Depth: 3"
 Maintenance appears: ☒ Good ☐ Fair ☐ Poor Depth of Tank Lid: 4 1/2 ft.

Type of System

- ☒ Septic Tank (# tanks 1)
☐ Cesspool
☐ Aeration System
☐ Other

Type of Tank

- ☐ Steel
☒ Concrete
☐ Fiberglass
☐ Other

Type of Absorption Area

- ☒ Leaching Field
☐ Raised Mound
☐ Seepage Pit (# pits)
☐ Other

SYSTEM COMPONENT

COMMENTS

TANK OR CESSPOOL Condition: <input checked="" type="checkbox"/> Acceptable <input type="checkbox"/> Unacceptable	TANK APPEARS TO BE IN GOOD CONDITION AT THIS TIME.
HOLDING TANK (if present) Condition: <input type="checkbox"/> Acceptable <input type="checkbox"/> Unacceptable <input type="checkbox"/> Not Applicable	
PUMP Condition: <input checked="" type="checkbox"/> Acceptable <input type="checkbox"/> Unacceptable <input type="checkbox"/> Not Applicable	PUMP STATION IS IN WORKING CONDITION AT THIS TIME
ABSORPTION SYSTEM Condition: <input checked="" type="checkbox"/> Acceptable <input type="checkbox"/> Unacceptable	SYSTEM APPEARS TO BE IN WORKING CONDITION AT THIS TIME.

THIS CONDITION REPORT INDICATES THE PRESENT CONDITION OF THE SEPTIC SYSTEM ACCORDING TO DRIVER OPINION. THIS CONDITION REPORT DOES NOT GUARANTEE OR WARRANTY FUTURE PERFORMANCE. HARTIGAN COMPANY DISCLAIMS ANY WARRANTY EITHER EXPRESSED OR IMPLIED ARISING FROM THE INSPECTION OF THIS SEPTIC SYSTEM OR THIS REPORT.

Hartigan Company
P.O. Box 1134
Stowe, VT 05672

Invoice

Date	Invoice #
4/5/2007	17613

Bill To
Lang, McLaughry, and Spera P.O. Box 539 Stowe, VT 05672

P.O. No.	Terms	Serviced by:	Service Date
Sherry Wilson	Net 15	W.Cyr	04/04/2007

Quantity	Description	Rate	Amount
	Driver's Comments: Could not see baffle Tank Condition: Good 2 hoses to reach tank from truck 3 year maintenance plan recommended by driver Disposal Location: Montpelier Wastewater Treatment Plant Depth of tank: 4.5" Sludge Level: 3" Cake Level: 3" Site Location: Leo & Marilyn Weiss 399 Subgroups Road Stowe, VT 05672 Pumped pumpstation 8' down to tank. Pumped septic tank, level: Normal but too deep to inspect baffles Reburied tank cover		
We will mail a reminder card in in 3 years.		Total	\$477.50

A service charge equivalent to 1 1/2% per month (18% annum)
will be added to past due accounts

Phone #	Fax #
802-253-0376	802-253-0387

Hartigan Company
P.O. Box 1134
Stowe, VT 05672

Invoice

Date	Invoice #
4/5/2007	17613

Bill To
Lang, McLaughry, and Spera P.O. Box 539 Stowe, VT 05672

P.O. No.	Terms	Serviced by:	Service Date
Sherry Wilson	Net 15	W.Cyr	04/04/2007

Quantity	Description	Rate	Amount
1,250	Residential Septic Tank - 1000 gallons	0.24	300.00
1	Backhoe service rental	177.50	177.50
We will mail a reminder card in in 3 years.		Total	

A service charge equivalent to 1 1/2% per month (18% annum)
will be added to past due accounts

Phone #	Fax #
802-253-0376	802-253-0387

(To be Filed in Duplicate)

Application No. H-10-80

Application Date 11-14-80

Fee (\$2.50) Paid 2.50 Ch. Bsa

BOARD OF HEALTH

Town and Village of Stowe

APPLICATION FOR PERMIT

Subsurface Sewage Disposal System

11-219

Applicant's Name Mr. and Mrs. Leo Weiss
Mailing Address 5512 Alpine, Cote St. Luc, Mtel, P.Q. Zip H42 2X1
Telephone Number 514-482-6341 Business Number 514-325-4000
Location of Property Sugar Hse. Hill, E4
(Be specific please)
New Construction ☒ Repair _____ Replacement _____
Number serviced by System: Kitchens 1 Dishwashers 1 Garbage Disposers 1
Baths 3 1/2 Showers (Separate) _____ Toilets 4 Bed Count _____
Restaurant Capacity _____ P

PLOT PLAN REQUIRED: The proposed Sewage Disposal System shall be shown on a plot plan of the property, showing separately the location of each part of the system; the buildings to be served; the adjoining roads or streets; adjoining property, dwellings, buildings, streams, water sources or lines and sewage disposal systems within 100 feet of any part of the Sewage Disposal System.

PERCOLATION TESTS: — (Locate on plot plan)

Test No. 1. _____ Boring log: —
Test No. 2. _____
Test No. 3. _____
Test No. 4. _____

0-1' WOOD DUFF
ETDPSOIL
1-6 SILTY SAND
6-7 1/2' SANDY SOIL
7 1/2' WATER AT
8' ADLTD.

I hereby certify that the above percolation tests and borings were taken (by me) (under my direction) and that this location (is) (is not) suitable for the purpose intended.

Date 11-15-79 _____
(Engineer) (Designator)

I swear, under the pains and penalties of perjury, that the statements contained in this application are true and complete to the best of my knowledge and belief.

Date 11/9/79 _____
Mr. and Mrs. Leo Weiss
Curtis & Bedell Inc.
Applicant's Signature

Application received by me 4/23, 1980

Approved ☒ Disapproved _____ Reason _____

(Health Officer) (Deputy Health Officer)

OFFICE COPY