

58 Center Rd
Middlesex, Vermont 05602

septic@kingsburyco.com
802-496-2205

Date of Service Wednesday • July 15, 2020

Time In / Out

Technician

Property Mary Brock
101 Guild Hill Rd
Waterbury Ctr, VT 05677-8046

Gal Pumped 1,000

BILL TO

Mary Brock
101 Guild Hill Rd
Waterbury Ctr, VT 05677-8046

TECHNICIAN NOTES

Dug inlet approximately 4-5' in ground. Tank is in good condition. Outlet baffle is poor condition.* Televised to home cast iron pipe into home recommended flushing because of scale. Customers approved so I jetted inlet many times to remove scale. Televised several times before getting it clear. Dug outlet televised 50' line looked good. Used locator to locate and televised in d box. Dug d box was 3-5' in ground and then televised laterals. First lateral led to another d box others tied back into one another it was very difficult to get around such hard 90 degree turns. System appears to function as designed at this time. No one has lived in home in three months according to customer.

NEXT SERVICE DUE IN 3 YEARS

SERVICES PERFORMED

Septic Pump 1000 Gal or Less	[1.00]	@ 350.00	350.00
Camera Line Inspection- 2hr min	[2.00]	@ 175.00	350.00
Skilled Labor - CB	[4.00]	@ 50.00	200.00
Mini Excavator	[1.00]	@ 250.00	250.00
Sewer Line & Drain Jetting -2hr min	[2.00]	@ 175.00	350.00
Cover	[1.00]	@ 80.00	80.00
6% Sales Tax	[1.00]	@ 4.80	4.80
Total			\$ 1,584.80
Amount Paid			\$ 1,584.80

BALANCE DUE



\$ 0.00

Customer Signature

Mary Brock

M 386-302-3272

PROPERTY:101 Guild Hill Rd
Waterbury Ctr, VT 05677-8046

BILLING:Mary Brock
101 Guild Hill Rd
Waterbury Ctr, VT 05677-8046

LAST SERVICE:

July 23, 2018

CONTACT NOTES:

JOB #:

154-720

PROPERTY NOTES:

JOB NOTES:

*Technician recommends installing outlet filter and basket to prevent solids from entering the d box.

JOB VOLUME: 1,000

GALLONS PUMPED: 1,000

INVOICE TOTAL: \$1584.80

TIME IN / OUT: _____

P	TANK NAME	TANK CAPACITY	SOURCE	TANK NOTES
	Tank 1	1,000 Gallons	Septic Tank	Filter: Unknown Concrete